

From: [Moore, Gary](#)
To: [Tighe, C. Daniel](#)
Subject: Re: CES Griggs Road VCP Site
Date: Tuesday, May 10, 2016 9:57:00 AM

Daniel

This is just overflow or is there a sump that we may have missed?

Sent from my iPhone

On May 10, 2016, at 6:51 AM, Tighe, C. Daniel <Daniel.Tighe@WestonSolutions.com> wrote:

Hey Gary,

The spot she is talking about was where ERRS had brought in sand during the ER. It's right at the corner and they had built a berm to stop the material that was leaking out of the drain from the secondary containment from flowing to the southwest corner.

If you remember, that area was filled with the goop that was coming out of that drain. So, I would presume, that the waste profile would be the same as was in the south tank secondary containment.

FT-5180 was just one of the multitude frac tanks. I think we just assumed it was CES's because it had no other markings.

Hope that helps!

Daniel

C. Daniel Tighe, PMP
Weston Solutions, Inc.
713.397.1550 cell
713.985.6763 direct

From: Moore, Gary [<mailto:Moore.Gary@epa.gov>]
Sent: Monday, May 09, 2016 5:50 PM
To: Tighe, C. Daniel <Daniel.Tighe@WestonSolutions.com>
Subject: Fwd: CES Griggs Road VCP Site

Daniel

Do you remember anything about the area discussed and picture provided?

Thanks

Gary

Sent from my iPhone

Begin forwarded message:

From: Brenda Basile <Brenda.Basile@pbwllc.com>
Date: May 9, 2016 at 4:54:31 PM CDT
To: "moore.gary@epa.gov" <moore.gary@epa.gov>
Subject: CES Griggs Road VCP Site

Gary:

The attached photo shows the location of the sand that is covering some hydrocarbon impacts. We are going to handle this but we would like to address all areas (if there are any more) that

have similar problems. If you have any information, I'd appreciate it so we can scope the work appropriately. I will follow-up with Terry Andrews and see if TCEQ has information about other locations that we should be aware of.

We are making use of the waste data you generated during the removal action to help with the waste unit closures. The waste in several tanks was nonhazardous so those units should not need to be closed as RCRA waste units.

We also have a question about the green frac tank left on the Site (see photo). You said this was owned by CES. The other three tanks (FT-1001, FT-1002, and FT-1004) were waste units listed on the TCEQ Notice of Registration. But we can't match up the green tank, FT-5180, with any of the waste units. The data show it had oily water. Did you have any other information or was this just one of the multitude of frac tanks?

Thanks for your help.

Brenda

BPB-eSig



+++++CONFIDENTIALITY NOTICE+++++

This e-mail and the information contained herein may be confidential and/or protected by the attorney-client, work product or other applicable privilege. This e-mail is intended to be reviewed only by the individual or organization named above. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination, or copying of any portion of this e-mail, and/or any attachments, is prohibited. If you have received this e-mail in error, please immediately notify the sender by return e-mail and delete this e-mail from your system. Thank You.

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.